Approved For Release 2004/1401 CLARDP78-04983A000100040018-5

## SECRET

	TO: Acting Chief, Real Estate and Construction Division THEW: Director of Logistics FROM: Construction Engineer, 25X1C4A	0
25X1A2D1	SUBJECT: General: Document No. 12  Specific: Replacement Construction Program Declassified  Declassified	the sale pair this talk and sep and a
25X1A6C	REF: Class. Changed You and	30
	ACTION REQUIRED: None, Information Date: 07/1/28	By: 02

25X1A2E

- 1. The comments and suggestions of contained in the reference have been noted with interest as a number of these points are in concert with considerations and discussions previously made in the field.
- s. The water line mentioned has been installed in a more direct route which will appear on the "As Built" drawings. Preservation of natural cover and accessibility were considered.
- b. All water sources are of critical contamination. Chlorination to the supply tank and to the booster pumps is therefore considered advisable in concurrence with Engineers recommendation

Past experience in the area indicates overheating of generating equipment by sheltering from prevailing winds. Thunderstorms are rare and it is desired to take full advantage of maximum ventilation. If found necessary, a louvre protection may be installed later on.

c. Plans do not call for sloping the tank floors as infrequent draining and cleaning will be done by brooming. However, this may be adjusted in the field if no additional cost is involved.

25X1A2D1

- d. We are advised that the redwood storm drain covers meet requirements and precludes use of weight handling equipment for maintenance.
- e. Drawing No. 699-585 indicates that drainage of the car shed and apron have been provided. Field adjustments will be made as necessary 25X1A to obtain adequacy.

20 March 1956

25X1A

25X1A

- f. The Receiver installation has been suspended pending conference ( No further information has been received at this Station. Request HOS advice SAP. The catenary clearance had been "caught" in the field.
- 2. A supply of cast iron pipe has arrived and utilities installations are progressing. It is not desired to encumber Headquarters with detail review of the utility plans, however, if any claring discrepancies are apparent, HQS advice Willed For Release 200 1/1/01 CIA-RDF78-04983400010000000 18-5 not be missed in the field. CONFEREN 25X1A9A